Number of non-collision franchised bus accidents involving passengers injured inside bus compartments in the past five years

Year	(i)	(ii)	(iii)	
	No. of non-collision	No. of accidents in	No. of accidents	
	franchised bus	(i) involving	in (ii) involving	
	accidents involving	passengers injured		
	passengers injured	on staircase	straight staircase	spiral staircase
	inside bus	(casualty)		
	compartments [@]			
	(casualty)			
2007	572 (588*)	158 (161)	21	137
2008	512 (530*)	132 (135)	14	118
2009	465 (488*)	148 (153)	23	125
2010	476 (496)	120 (122)	12	108
2011	512 (532**)	149 (151*)	22	127
(provisional				
figures)				

Non-collision franchised bus accidents involving passengers injured inside bus compartments were mainly caused by passengers not holding the handrail or emergency braking by drivers.

^{*} Amongst one passenger died.

^{**} Amongst two passengers died.