


Lack of secure support for scaffold

In contravention of Regulation 38D of the Construction Sites (Safety) Regulations



Angle bracket supporting the truss-out scaffold on the external wall is not fixed with sufficient anchor bolts