

**Annex 2****Service disruptions of 31 minutes or above outside the control of MTRCL  
from 2012 to March 2014**

<b>Date</b>	<b>Cause</b>	<b>Process</b>	<b>Delay Time (minutes)</b>
<b>2012</b>			
April 3	External factor	Due to a dump truck's jumping of red light at the junction of Castle Peak Road and Tin Ha Road in Yuen Long and its collision with an approaching Light Rail vehicle, Light Rail service between Tuen Mun and Yuen Long/Tin Shui Wai was suspended.	54
April 19	Passenger's behaviour	Due to a passenger's jumping onto the track at University Station of East Rail Line, train service was delayed.	38
April 29	Passenger's behaviour	Due to a passenger's failure to follow traffic light signal when crossing the junction of Ming Kam Road and Shek Pai Tau Road and his hitting by an approaching Light Rail vehicle, Light Rail service in Tuen Mun area was suspended.	31
July 23	External factor	Service of East Rail Line was suspended as Severe Typhoon Vicente brought down a number of trees which damaged the overhead lines.	476
July 24	External factor	Light Rail service was suspended as Severe Typhoon Vicente brought down a number of trees which damaged	264

Date	Cause	Process	Delay Time (minutes)
		the overhead lines at San Hui Stop.	
September 29	External factor	Train service of East Rail Line was delayed by a faulty Mainland Through Train stalling near Tai Wai Station.	35
<b>Total:</b>			<b>6 incidents</b>
<b>2013</b>			
March 16	Passenger's behaviour	Due to a passenger's jumping onto the track at University Station of East Rail Line, train service was delayed.	44
June 14	External factor	Due to a taxi's jumping of red light at the junction of Tin Sau Road in Tin Shui Wai and its collision with an approaching Light Rail vehicle, Light Rail service was delayed.	43
June 30	Passenger's behaviour	Due to a passenger's jumping onto the track at Tai Wai Station of East Rail Line, train service was delayed.	50
August 19	Passenger's behaviour	Due to a passenger's failure to follow traffic light signal when crossing the junction of Tin Yiu Road and Tin Wu Road in Tin Shui Wai and his hitting by an approaching Light Rail vehicle, Light Rail service between Tin Yiu and Tin Shui stops was suspended.	176
September 19	External factor	Train service of East Rail Line was delayed because a sky lantern entangled in a pantograph of a train when it arrived at Sheung Shui Station and tripped the overhead line traction current supplies.	31
September 22	External factor	Light Rail service in Tuen Man area was suspended as	219

Date	Cause	Process	Delay Time (minutes)
		Super Typhoon Usagi brought down a number of trees which damaged the overhead lines.	
September 24	Passenger's behaviour	Due to a passenger's jumping onto the track at University Station of East Rail Line, train service was delayed.	53
October 7	External factor	Due to damage of the overhead lines at the junction of Hing Choi Street and Tsing Wun Road in Tuen Mun by the crane of a dumper truck crossing the junction, Light Rail service between Melody Garden and Shek Pai stops was suspended.	267
November 2	External factor	Due to a taxi's jumping of red light at the junction of Castle Peak Road and Tin Ha Road in Yuen Long and its collision with an approaching Light Rail vehicle, Light Rail service was delayed.	41
November 8	Passenger's behaviour	Due to a pedestrian's failure to follow the traffic light signal when crossing the junction of Melody Garden and Wu Chui Road and his hitting by a Light Rail vehicle, Light Rail service between Tuen Mun Ferry Pier and Light Rail Depot stops was suspended.	37
December 8	External factor	Due to a taxi's intruding into Light Rail reserve area together with its hitting of an overhead line mast and a traffic signal pole at the junction of Pui To Road, Tsing Wun Road and Ming Kum Road in Tuen Mun, Light Rail service between Melody Garden and Tsing Wun	44

<b>Date</b>	<b>Cause</b>	<b>Process</b>	<b>Delay Time (minutes)</b>
		stops was suspended.	
<b>Total:</b>			<b>11 incidents</b>
<b>2014 (up to end March)</b>			
January 31	External factors	Due to a car's jumping of red light at the junction of Wu Chui Road and Lung Mun Road in Tuen Mun and its collision with an approaching Light Rail vehicle, Light Rail service between Melody Garden and Light Rail Depot stops was suspended.	46
<b>Total:</b>			<b>1 incident</b>