

# No personal fall protection equipment

In contravention of Regulation 38B of the Construction Sites (Safety) Regulations



The scaffolder is not provided with a safety belt and an independent lifeline