

Annex

Cases of Road Subsidence on Public Roads between 2021 and 2023

| Year | Cause | Number of case | Location | Area of road subsidence (square metre) |
|---------------|--|-----------------------|--------------------------|---|
| 2021 | Damage of underground pipework facilities (including water mains and drainage pipes, etc.) | 8 | Peak Road | 12 |
| | | | Pui Ching Road | 5 |
| | | | Kansu Street | 5 |
| | | | Texaco Road | 3 |
| | | | Shek Po Road | 30 |
| | | | Tin Ying Road | 28 |
| | | | Lower Shing Mun Road | 27 |
| | | | Che Kung Miu Road | 6 |
| | Improper backfill after road excavation works by public utility companies | 2 | Man Cheong Street | 2 |
| | | | Jordan Valley North Road | 2 |
| | A number of factors were involved and the cause could not be determined | 4 | Tung Choi Street | 5 |
| | | | Lai Yip Street | 11 |
| | | | Ngau Tau Kok Road | 3 |
| Ting Kok Road | | | 2 | |
| 2022 | Damage of underground pipework facilities (including water mains and drainage pipes, etc.) | 12 | Tai Cheong Street | 1 |
| | | | Choi Ha Road | 6 |
| | | | Wan Po Road | 20 |
| | | | Che Kung Miu Road | 2 |
| | | | Plover Cove Road | 2 |

| Year | Cause | Number of case | Location | Area of road subsidence (square metre) |
|-------------|--|-----------------------|----------------------|---|
| | | | Tai Chung Kiu Road | 9 |
| | | | Sai Lau Kok Road | 6 |
| | | | Sai Lau Kok Road | 4 |
| | | | Shek Yam Road | 16 |
| | | | Wan Po Road | 5 |
| | | | On Po Road | 2 |
| | | | Lower Shing Mun Road | 70 |
| | A number of factors were involved and the cause could not be determined | 4 | Kennedy Road | 6 |
| | | | Tai Tam Road | 1 |
| | | | Lung Hop Road | 2 |
| | | | Kwai Ting Road | 1 |
| 2023 | Damage of underground pipework facilities (including water mains and drainage pipes, etc.) | 13 | Wong Chuk Hang Road | 16 |
| | | | Wong Chuk Hang Road | 20 |
| | | | Nelson Street | 2 |
| | | | Hoi Wang Road | 16 |
| | | | Mong Kok Road | 8 |
| | | | Soy Street | 4 |
| | | | Che Kung Miu Road | 4 |
| | | | Castle Peak Road | 12 |
| | | | Kwong Fuk Road | 1 |
| | | | On Shing Street | 16 |

| Year | Cause | Number of case | Location | Area of road subsidence (square metre) |
|--------------|---|-----------------------|----------------------|---|
| | | | Sha Tau Kok Road | 2 |
| | | | Tai Wo Road | 6 |
| | | | Kwai Wing Road | 1 |
| | Related to the foundation works being carried out nearby | 4 | Hok Yuen Street | 12 |
| | | | Lin Cheung Road | 6 |
| | | | On Sau Road | 2 |
| | | | Kam Ho Road | 4 |
| | A number of factors were involved and the cause could not be determined | 5 | Po Kong Village Road | 2 |
| | | | Canton Road | 4 |
| | | | Graham Street | 6 |
| | | | Hing Fong Road | 1 |
| | | | Hing Fong Road | 1 |
| Total | | | | 52 |

Note: The Government does not keep information on the number of persons affected in each case.