Contents

			Page
1	INTR	1	
	1.1	Project Background	1
	1.2	Objectives of the Report	2
	1.3	Structure of this Report	3
	1.4	Nomenclature and Abbreviations	3
2	PROJ	5	
	2.1	Site Location	5
	2.2	Existing Conditions	5
	2.3	The Preferred Option	5
	2.4	The Project Site Boundary	6
	2.5	Land Use Budget	6
	2.6	Proposed Development of the PH Site	7
	2.7	Proposed Development of the YLIEE Site	10
	2.8	Tentative Implementation Programme	11
3	SITE DESCRIPTION		12
	3.1	The Study Area	12
	3.2	Natural Terrain Hillsides	12
4	DESK STUDY		15
	4.1	Approach and Data Sources	15
	4.2	Topographic Setting	16
	4.3	Published Geological Information	18
	4.4	Ground Investigation Data	18
	4.5	Boulder Field Inventory	19
	4.6	Instability Records	19
	4.7	Registered Man-made Features	21
	4.8	Aerial Photograph Interpretation	22
5	ENGINEERING GEOLOGICAL ASSESSMENT		23
	5.1	Solid Geology	23
	5.2	Superficial Geology	23
	5.3	Uncertainties in the Ground Model	23
6	NATU	24	
	6.1	Enhanced Approach to NTHS	24
	6.2	Detailed Field Mapping	24
	6.3	Natural Terrain Hazard Susceptibility	25
	6.4	Landslide Consequence	30

	REFERENCES		38 39
	CLUSIONS AND RECOMMENDATIONS		
	7.2	Possible Hazard Mitigation Strategy	37
	7.1	Hazards to be Mitigated	37
7	MITI	37	
	6.5	Landslide Design Event	30