



Figure 1: Photo showing the extent of damage to the part of Sea Smooth involved in the collision



Figure 2: Photo showing the extent of damage to the part of Sea Smooth involved in the collision



Figure 3: Photo showing the extent of damage to the part of Sea Smooth involved in the collision



Figure 4: Photo showing the extent of damage to the part of Sea Smooth involved in the collision



Figure 5: Photo showing the extent of damage to the part of Sea Smooth involved in the collision

Ends