



FSD Inspections to the Fire Service Installations of CHT

消防處檢查海底隧道的消防裝置及設備

Testing of various fire hydrants of the tunnel
測試隧道內不同的消防栓



at the portal
在隧道入口



inside the tunnel
在隧道內



FSD Inspections to the Fire Service Installations of CHT

消防處檢查海底隧道的消防裝置及設備

Inspection at the tunnel:
檢查隧道內：

Fire Alarm System
火警警報系統

Emergency Telephone
緊急通訊電話裝置





FSD Inspections to the Fire Service Installations of CHT

消防處檢查海底隧道的消防裝置及設備

Inspection at the tunnel:
檢查隧道內：

**Automatic Foam Fire
Fighting Installation**
自動泡沫救火裝置





FSD Inspections to the Fire Service Installations of CHT

消防處檢查海底隧道的消防裝置及設備

Inspection at the tunnel:
檢查隧道內：

**Fire extinguishers were
found missing**
滅火筒被取去





FSD Inspections to the Fire Service Installations of CHT

消防處檢查海底隧道的消防裝置及設備

**Inspection at
Ventilation Buildings**
檢查通風大樓



**Inspection to FS panel in
South Ventilation Building**
檢查南通風大樓的消防控制板



**Inspection to FS panel in
North Ventilation Building**
檢查北通風大樓的消防控制板



FSD Inspections to the Fire Service Installations of CHT

消防處檢查海底隧道的消防裝置及設備



**FSD officers inspect the Fire Service
Installations of the Tunnel Control Room**
消防處人員檢查行政大樓控制中心的消防
裝置及設備




Fire hydrant/hose reel system were tampered
消防栓／喉轆系統被破壞




FSD Inspections to the Fire Service Installations of CHT

消防處檢查海底隧道的消防裝置及設備

Toll booths
收費亭



Portable fire extinguishers
手提滅火筒





FSD Inspections to the Fire Service Installations of CHT

消防處檢查海底隧道的消防裝置及設備

Inspection at toll booths:
檢查收費亭

Fire extinguishers were found missing
滅火筒被取去





FSD Inspection to the Administration Building of the tunnel (21.11.2019)

消防處檢查海底隧道的行政大樓 (21.11.2019)

FSIs reinstated
已修復的消防設備

FH/HR system
消防栓／喉轆系統





消防車輛及救護車輛在海底隧道(九龍入口)停泊之位置





Fire Appliances and Ambulance Staging Point (Hong Kong Island Portal)

消防車輛及救護車輛在海底隧道(香港入口)停泊之位置

