

Annex 1

Number of complaints about
the ancillary facilities of cycle tracks in the New Territories
in the past three years

Type of complaint	2018	2019	2020
Cycle track design/safety facilities	32	29	50
Design of pedestrian crossing points and cycle track/road junctions	11	17	17
Continuity of cycle tracks	4	2	6
Bicycle parking area	16	18	23
Others (including illegal parking of bicycles, bicycle direction signs, temporary traffic arrangements on cycle tracks, etc.)	28	23	17
Total	91	89	113